

# Mounting Instruction

## SHV Cable Jack + Cable RG 58

**1** Remove the cable sheath




**2** Push back the braided shield and strip the isolation from the center conductor




**3** Push back the screen to the front end and twist it together




**4** Put on the cable the screws, metal washer, clamping rubber and taper washer



**5** Push back the braided shield and cut it along the outside of the taper washer



**6** Solder the center contact



**7** Push the parts together and screw them together

